




The Viking Corporation | 210 N Industrial Park Drive | Hastings MI 49058
 Viking Special Hazards | Technical Services: 877-384-5464 | Email: techsvcs@vikingcorp.com | www.vikinggroupinc.com
 The technical data described herein is for components of the Viking Oxeo PR Fire Suppression Systems.
 Visit the Viking website for the latest edition of the technical data and system manuals.

1. DESCRIPTION

Viking Oxeo Fire Suppression Systems require warning signs to be attached to all access doors to identify the protected enclosure, warning of the existence of an Oxeo fire suppression system and the risks involved. Two types of signs are required (refer to Figures 1 and 2):

- Outside Warning Sign
- Inside Warning Sign

2. LISTINGS AND APPROVALS



cULus Listed - EX5248 (Oxeo PR LCP, and VSH1230)

FM Approved: Oxeo PR LCP and VSH1230

3. TECHNICAL DATA
Specifications


- Warning Sign Types: Refer to Figures 1 and 2.
- Dimensions: 10" (254 mm) W x 10" (254 mm) H

Material Standards

Aluminum Plate

Ordering Information

- To order Warning Signs for the Oxeo Nitrogen Fire Suppression System: Refer to part number 24587 (24587-S Spanish; 24587-F French) for the Outside Warning Sign and part number 24588 (24588-S Spanish; 24588 F-French) for the Inside Warning Sign.
- To order Warning Signs for the Oxeo Argon Fire Suppression System: Refer to part number 24589 (24589-S Spanish; 24589-F French) for the Outside Warning Sign and part number 24590 (24590-S Spanish; 24590-F French) for the Inside Warning Sign.





TECHNICAL DATA


OXEO WARNING SIGNS

The Viking Corporation | 210 N Industrial Park Drive | Hastings MI 49058

Viking Special Hazards | Technical Services: 877-384-5464 | Email: techsvcs@vikingcorp.com | www.vikinggroupinc.com

The technical data described herein is for components of the Viking Oxeo PR Fire Suppression Systems.

Visit the Viking website for the latest edition of the technical data and system manuals.



Part No. 24589: Outside Warning Sign



Part No. 24590: Inside Warning Sign

Figure 2: Oxeo Argon System Warning Signs - Identification for the Protected Area